

Material Thickness vs. Maximum OAH for rolled parts in Large Roll & Weld Cell

Note: If there are one or two flanges, the max OAH of the part will decrease by the sum of the widths of each flange.

